

15.1 WALLS (Report signs of missing, non -uniformly distributed, marginal, or wet thermal insulation)

Comments: Repair

RR: A section of the upper wall in the Living room is missing insulation. An infrared thermal imaging camera was used to scan the wall. The thermal image below shows heat gain (loss) at the upper section of the wall. I recommend installing insulation behind the wall for improved energy efficiency.

