

January 2005



Picture 1

New concrete piers on top of concrete footings--no soil to hold footings in place.




Picture 2

Splash guard in place on top of a flat roof.



Picture 3

Dryer flue to exterior of garage. Vent hood was three feet away at left.



Picture 4

Protective enclosure for electric panel to prevent moisture penetration.

The HomeTeam Inspection Service · San Diego, California · 888-488-TEAM · www.BuyerPeaceOfMind.com
 National Association of Certified Home Inspectors (www.nachi.org) · Better Business Bureau (www.sandiego.bbb.org)

SUNDAY	MONDAY	TUESDAY	WEDNESDAY	THURSDAY	FRIDAY	SATURDAY
						1
2	3	4	5	6	7	8
9	10	11	12	13	14	15
16	17	18	19	20	21	22
23	24	25	26	27	28	29
30	31					