

# January 2005



Picture 1

New concrete piers on top of concrete footings--no soil to hold footings in place.




Picture 2

Splash guard in place on top of a flat roof.



Picture 3

Dryer flue to exterior of garage. Vent hood was three feet away at left.



Picture 4

Protective enclosure for electric panel to prevent moisture penetration.

| SUNDAY | MONDAY | TUESDAY | WEDNESDAY | THURSDAY | FRIDAY | SATURDAY |
|--------|--------|---------|-----------|----------|--------|----------|
|        |        |         |           |          |        | 1        |
| 2      | 3      | 4       | 5         | 6        | 7      | 8        |
| 9      | 10     | 11      | 12        | 13       | 14     | 15       |
| 16     | 17     | 18      | 19        | 20       | 21     | 22       |
| 23     | 24     | 25      | 26        | 27       | 28     | 29       |
| 30     | 31     |         |           |          |        |          |