

Inspection Address: [REDACTED]
Inspection Date/Time: [REDACTED]

Return-Air Compartment

Components and Conditions Needing Service

[REDACTED]

The dryer vent passes through the return-air compartment, which could allow gas dryers to contaminate the circulating air with the bi-products of combustion, and gas or electric dryers to produce a humid environment in molds could flourish. Therefore, the vent should be isolated within the return-air compartment, or rerouted.



[REDACTED]



[REDACTED]